

28 DEC 1983

REAL ESTATE AND CONSTRUCTION DIVISION WEEKLY REPORT
FOR PERIOD ENDING 28 DECEMBER 1983

1. Progress Report Tasks Assigned by the DCI/DDCI:

None

2. Items or Events of Major Interest that Have Occurred During the Preceding Week:

STAT Map Library- [] - On 26 December, 1983, two water lines burst due to freezing and caused considerable damage to the entire Map Library area.

One water sprinkler line burst outside the leased area and as a result the water flowed into the library area and wet the carpet and caused some minor partition damage.

STAT Another pipe burst [] which is above the map cabinet area. This water leaked through the ceiling which resulted in ceiling tile damage and created a water level of 3-4 inches on the floor.

STAT [] Management did take immediate action by having a cleaning crew that worked all that night and part of the next day.

There is a work crew that is presently drying out the carpeting. Based on the D/L's suggestion, it is possible to dry out the carpeting under the large map cabinets by removing one or two lower drawers.

Since most of the telephone conduits and outlets have been dried out, most of the employees are back at work.

STAT SIAI Another major problem that requires further investigation is a floor slab that has receded approximately two inches. []

3. Significant Events Anticipated During the Coming Week:

None

STAT